## Schork Inspection Services Inc. Specializing In Wood Destroying Organism Inspections 2209 Springwood Court Santa Rosa Ca. 95403 Phone 571-8177 Fax 527-9444

## Guideline Cost

Date 07/10/2018

TO Mary Haufler Sotheby's International 401 Chinn Santa Rosa Ca. 95404

PROPERTY ADDRESS: 4721 Starbuck Ave. Santa Rosa Ca. 95409

The following are minimum guideline cost to repair, or treat, some or all (Section One) items of the main structure residence report dated 0710/2018 for the property listed above. These are only guideline figures and not a bid for work, or contract to do work.

 These guideline figures are intended as a guide for securing bids from contractors only, and should not be used for negotiation purposes. You are advised to contact a licensed general building contractor familiar with wood destroying organism's repair, for an accurate bid on the repairs outlined in the report. <u>Estimates listed below do not include</u> the added cost of possible lead paint remediation. Parties of interest should contact a lead paint remediation specialist regarding lead paint issues and repair processes. Schork Inspection Services Inc. does not perform corrective repairs.

Minimum Guideline Cost 1A. 450.00 1B. 750.00 4A. 780.00

 All Guideline figures are based on a time and materials cost basis, with a minimum starting cost, unless stated otherwise. Hidden damage found during the repair process is considered an extension of repair into inaccessible areas, is subject to further inspection and evaluation during repair process, and will include cost adjustments. <u>All of the guideline figures listed above do not include cost for remediation of lead based paint as they may relate to repairs of this structure.</u> If you are concerned about lead based paint issues, you should consult with a contractor and or specialist in the field of lead paint abatement issues.

Thank you

Lawrence J. Schork Schork Inspection Services Inc. cc: file corrected 1C. to \$350.00